

Accessories

**GMK 38**

Connection cable
(BNC to 2 x banana plug) approx. 90 cm long

GHE 91

Reciprocating piston electrode *
to drive measuring nails into material without auxiliary devices

GSE 91

Impact electrode *
to drive measuring nails into material

GEG 91

Handle
suitable for GSE 91

GSG 91

Penetration electrode *
adequate for steel nails and measuring rods

GST 91

steel nails
9 steel nails (3 pieces each, 12, 16 and 23 mm long) in plastic case, Ø 2.5 mm

GST 91/40

steel nails
10 steel nails, 40 mm long, Ø 2.5 mm, in plastic case

GST 45i

steel nails
2 Teflon isolated steel nails, 45 mm long, Ø 2.5 mm

GST 60i

steel nails
2 Teflon isolated steel nails, 60 mm long, Ø 2.5 mm

GOK 91

measuring cap
Surface measuring caps (pair)
(for use with GSG 91 or GSE 91)

GMS 300/91

Measuring rods
300 mm long (pair), for wood chips, wood wool, paper, carton, etc. (for use with GSG 91 or GSE 91)

GST 15B

steel nails *
2 steel nails with bore hole, 15 mm long, Ø 3.8 mm (for direct connection of measuring cable GMK 38)

GST 25B

steel nails *
as above, Ø 3.8 x 25 mm

GST 40B


steel nails *
as above, Ø 3.8 x 40 mm

GBSK 91

Wire brush (pair) short *
for depths up to approx. 100 mm

GBSL 91

Wire brush (pair) long *
for depths up to approx. 300 mm

**GEF 38**

Flat electrode (pair) *
for screed, paper, etc.

GLP 91

conducting paste *
100 ml, for surface measurements and depth indication in walls, wash floors etc. with brush probes

GSP 91

sensor for surface measurements *
on paper, textiles etc.

GSP 91 ES

spare sensor element
for GSP 91

**GSF 50 (110 cm)
GSF 50K (43 cm)**

Injection probe
(without temperature sensor) for measurement up to a depth of 40 cm or 107 cm, incl. 1 m connection cable. Suitable for: wood chips, wood wool, straw, hay, grain, saw dust, etc.

**GSF 50TF (110 cm)
GSF 50TFK (43 cm)**

Injection probe
(with temperature sensor) for measurement up to a depth of 40 cm or 107 cm, incl. 1 m connection cable. Suitable for: wood chips, wood wool, straw, hay, grain, saw dust, etc.

GSF 40 (67 cm)

Injection probe
(without temperature sensor) for measurement of pressed bales up to a depth of 60 cm, incl. 1 m connection cable. Suitable for: pressed hay or straw bales, grain

GSF 40TF (67 cm)

Injection probe
(with temperature sensor) for measurement of pressed bales up to a depth of 60 cm, incl. 1 m connection cable. Suitable for: pressed hay or straw bales, grain

GTF 38

NiCr-Ni temperature probe
voltage-free, Ø 2.2 x 25 mm, 1 m cable
(recommended for wood moisture measurements)

GES 38

NiCr-Ni injection probe
voltage-free, Ø 4 x 150 mm, 1 m cable
(recommended for wood moisture measurements)

GPAD 38

Test adapter
(with 2 reference values) for testing GMH 38xx and GMR 110

GKK 3500

Plastic case
(394 x 294 x 106 mm) with cut-outs for device and accessories

ST-RN

Protection bag
with blanked out sensor connections
(suitable for GMH 3830, GMH 3850)

Pict.: GMH 3830 in ST-RN

* Measuring cable necessary for GHE91, GSE 91, GSG 91, GST 15B / 25B / 40B, GBSK 91, GBSL 91, GEF 38, GLP 91, GSP 91